

Department: Sawmill
Reports to: General Manager

FLSA Status: Non Exempt
Date: August 21, 2019

EEO: 7, 51-7041, 8530

POSITION SUMMARY:

The Edger Operator safely operates and maintains the Edger equipment.

ESSENTIAL FUNCTIONS:

The duties identified below are the essential functions of the position. Employees must be able to fulfill these functions in a consistent state of alertness and in a safe manner. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

- Conduct activities in a safe manner, follow corporate safety guidelines and requirements, use personal protective equipment and proactively address any unsafe conditions observed. Maintain housekeeping and safety compliance, inspection ready at all times
- Responsible for setting up machines, maintaining process flow, shutting down machines, and performing maintenance as necessary
- Provide Headsaw and Resaw with steady flow of logs.
- Watch for situations that may develop and notify Resaw Operator with trouble light
- Cleans and inspects machinery daily
- Communicates with others on the line to facilitate production
- Keeps workspace and surroundings clean and neat to foster productivity and efficiency
- Other assignments as made by management

QUALIFICATIONS:

To perform this position successfully, an individual must demonstrate regular, predictable attendance and be able to perform each essential duty satisfactorily. The requirements listed below are representative of the knowledge and skill required. The individual must be able to successfully pass background checks.

- Teamwork: Can work in group or alone; oriented towards the good of the whole. Contain ability to build rapport and good working relationship with co-workers

EDUCATION/CERTIFICATION/LICENSURE:

- High School diploma or GED preferred

EXPERIENCE REQUIRED:

- Previous experience with setting up and maintaining equipment preferred
- Previous sawmill experience preferred

KNOWLEDGE AND SKILLS REQUIRED:

- Basic mechanical skills
- Able to read measuring devices